Service Information

TITLE : HWA 6D, HWA 14D new pump

MODEL : HWA 6D, HWA 14D

DATE : 2022-11-23 **NUMBER :** SI 221123

Reason for sending you this information

We have changed the pump of the HWA 6D and HWA 14D machines due to some issues with the pump.


Cause:
The old pump was in some cases causing extra noise and unintended error 9 messages.

Solution:
The new pump doesn't fit directly on earlier produced machines and because of this we have created a rebuild set of the new pump with some additional parts so that it can be used in earlier produced machines.

Part information:

The first new pump (6,236,839,000) is used in machines starting with serial number ***020002346799***

Position of the identification plate with the serial number



An instruction on how to replace the new pump for the old pump is supplied with the rebuild pump set.
This instruction can also be found on our website: 700.407.036

New Spare Part:

- 6.236.839.000 pump (new)
- 6.000.236.127 conversion kit pump HWA 6D/14D

Deleted Spare Part:

- 6.236.667.000

Copyright Bravilor Bonamat 2022
All Rights Reserved