

TITLE: Software Log**MODEL:** Bolero Turbo (XL)**DATE:** 2026-04-16**Reason for sending you this information**

For our Bolero Turbo (XL) machines we have the following updates of the software.
The updates for the Bolero are available by type and can be downloaded from our website.

HMI firmware		HMI firmware	
Item no:	002.071.046 / 002.071.053	Item no:	002.071.046 / 002.071.053
Type:	All	Type:	All
2026-04-16	1.1.0	2025-06-05	1.0.3
2026-01-06	1.0.6	2025-04-01	1.0.2
2025-12-05	1.0.5	2025-02-12	1.0.1
2025-11-27	1.0.4	2024-12-11	1.0.0

HMI firmware version 1.1.0 (16-04-2026)

- Added : Languages (Czech, Slovak, and Hungarian)
- Changed : QR code for cleaning instruction.
- Fixed : False error 8.

The first serial number produced with this update: **10098059**

HMI firmware version 1.0.6 (06-01-2026)

- Memory errors caused by temperature differences have been fixed.
- Resolved a crash that occurred when loading screensaver images that were too large.
- Erroneous visual effects have been corrected.

The first serial number produced with this update: **10095577**

HMI firmware version 1.0.5 (05-12-2025)

- version skipped, not released.

HMI firmware version 1.0.4 and 1.0.5 (27-11-2025)

- version skipped, not released.

HMI firmware version 1.0.3 (05-06-2025)

- Software change which solves the machine from unintended restarting, due to a higher motor currency load.

The first serial number produced with this update: **10044126**

HMI firmware version 1.0.2 (01-04-2025)

- Changes made to creating the EVA-DTS report, preventing the software to crash and restart.

The first serial number produced with this update: **10039256**

TITLE: Software Log

MODEL: Bolero Turbo (XL)

DATE: 2026-04-16

Reason for sending you this information

For our Bolero Turbo (XL) machines we have the following updates of the software.
The updates for the Bolero are available by type and can be downloaded from our website.

HMI firmware version 1.0.1 (12-02-2025)

- Changes made to the descaling instructions. The wrong amount of descaling agent and water was mentioned.

The first serial number produced with this update: **10034772**

HMI firmware version 1.0.0 (11-12-2024)

- *This modification relate to all Bolero Turbo (XL) machines with touch screen.*

- start first production
-