

TITLE : Software Log**MODEL**: FM100 / FM121 / FG100 / FG121 / FG143**DATE** : 2026-03-12

Reason for sending you this information

For our FreshBrew NG machines we have the following updates of the software.
The updates for the FreshBrew NG are available by type and can be downloaded from our website.

Release date	002.071.040
2026-03-02	1.1.3
2026-01-16	1.1.2
2025-12-01	1.1.1

Software package version 1.1.3 (03-02-2026)**Changes:**

- Correct saved location during first installation.

► This update is included in machines *after* serial number: 10121863

Software package version 1.1.2 (16-01-2026)**Fixed:**

- As ingredient calibrations were not stored, they returned to their default settings after a power cycle.
- The customised background, screensaver and logo were reset after a power cycle.
- Leakage detection was only carried out once.
- Leakage detection being delayed an extra 20 seconds after the boiler was considered 'full'.
- The recipe editor now allows editing hot-water sequences.
- After exiting the recipe editor via the dashboard, the available sequences for the recipe were not cleared, resulting in empty tabs from the previous recipe being displayed in the editor.
- Changing the waste-bin average #cups using the plus or minus button changed the value on the screen, but the new value was not actually set.

Changes:

- Check 'temperature rising while heating not engaged', but only if the boiler is full.

► *This update was not implemented, but has been included in version 1.1.3.*

Software package version 1.1.1 (01-12-2025)**Added:**

- Connected devices: payment devices.
- User level with pin codes.
- Recipe editor 2.0.
- Allow importing 'update' images. This allows the operator to import new default settings after updating the software, without losing alterations and customizations performed by the customer, except for settings that are not compatible with the new software.

Changes:

- Cleaning instructions.
- Downgrading to software images with versions lower than 1.1.1 from USB, as well as importing settings from software images with versions lower than 1.1.1, has been made impossible.
- Lower the brewer's idle position, to have less coffee buildup between the grinder outlet and the brewer inlet.

► This update is included in machines *after* serial number: 10098130